

Dear Vista x64 users,

To use Jump-Track 3 on Vista x64 please verify and follow the guidelines below:

1)

Contact Larsen & Brusgaard to receive a USB-Track interface unit that supports x64  
The USB-Track interface that is included with the Jump-Track 3.0 CD-ROM will not work  
(Do NOT connect USB-Track device before all program and updates are installed.)

2)

The following software is required:

[www.l-and-b.dk/jumptrackv3/JumpTrack\\_3\\_2.zip](http://www.l-and-b.dk/jumptrackv3/JumpTrack_3_2.zip)

PLEASE NOTE THAT JUMP-TRACK V3.0 MUST BE INSTALLED BEFORE UPDATING TO V3.2

2.1)

Download the zip file into an empty directory

2.2)

Unzip the 3 files

Jumptrack.exe

AltiTrack\_Communicator.exe

AltiTrack\_Firmware\_Programmer.exe

2.3)

Replace

..\Program Files\Jump-Track 3\Jumptrack.exe

with the new Jumptrack.exe

When running verify that it's version 3.20.A

Replace

..\Program Files\Jump-Track 3\Tools\Alti-Track Communicator\AltiTrack\_Communicator.exe

with the new AltiTrack\_Communicator.exe

When running verify that it's version 3.20.A

Replace

..\Program Files\Jump-Track 3\Tools\Alti-Track Firmware Programmer\AltiTrack\_Firmware\_Programmer.exe

with the new AltiTrack\_Firmware\_Programmer.exe

When running verify that it's version 3.20.A

3.1)

Download the verified Vista x64 drivers from the following link:

<http://www.ftdichip.com/Drivers/CDM/CDM%202.04.06%20WHQL%20Certified.zip>

and unzip to a temp. folder on desktop

3.2)

Connect USB device. Drivers are now installed automatic, if not then use "Device Manager" for manual install.

A Windows XP Installation Guide can be found here:

[www.l-and-b.dk/jumptrackv3/Windows\\_XP\\_Installation\\_Guide.pdf](http://www.l-and-b.dk/jumptrackv3/Windows_XP_Installation_Guide.pdf)

(Sorry, no Vista guide yet)

3.3)

Delete temp. folder

3.4)

Enjoy

Med venlig hilsen/ Regards

Steffen kristensen

Larsen & Brusgaard

[www.l-and-b.dk](http://www.l-and-b.dk)